TARIA	Brandenburg-Briest Airfield	and distributes of
TOPIC	DE QUOCALIMITE AND LOSS VILLISTO	10 Min Jake Macros & end
CONTRACTOR OF THE PROPERTY OF		PROGRAM MEN. MS
EVALUATION		NAME OF THE PERSON
DATE OF	CONTENT_ 2 to 31 October 1952 25X1	alatan meranika ana
DATE OBT	25X1 AINED	William to Mark Man
REFEREN	CES	
		etropher companie with 1724 and
PAGES	ENCLOSURES (NO. & TYPE)	
REMARKS		ESTERNA AND BUT
MOT PERMITETURES FEOREST AND TH	ILILITUL UUI I	ech in Maraka and
	DO NOT CIRCULATE	
Ode middles servi harbestanin hibrary o		t to 2 to Lamedo Atto
and an inter-order of the contract of the cont		ryc mous re
.1		
	As a second of the second of t	
	2 October, At 0:30 a.m., two MiG-15s took off to circle over the field. The ceiling was at an altitude of about 1,500 meters, and visibility was 5.000 meters. From 9:41 to 10:17 a.m., MiG-15s practiced formation flying. After landing, they taxied back to the take-off point and refueled from four tank trucks between 10:25 and 10:45 a.m. At 10:55, the planes again took off at intervals of about 100 meters. Heavy	2
(1 · · · · · · · · · · · · · · · · · · ·	ceiling was at an altitude of about 1,500 meters, and visibility was 5,000 meters. From 9:41 to 10:17 a.m., MiG-15s practiced formation flying. After landing, they taxied back to the take-off point and refueled from four tank trucks between 10:25 and 10:45 a.m. At 10:55, the planes again took off at intervals of about 100 meters. Heavy flying by MiG-15s continued until h p.m. At 6:05 p.m., two of the six alert planes took off and landed again at 6:13 p.m. 3 October. There was no flying. 4 October. After 8:30 a.m., six MiG-15s were successively towed by a truck to the target range in forest district 50, from where short bursts of mechine gum fire were subsequently heard. After 1 p.m., all MiG-15s were towed by two trucks	
1	ceiling was at an altitude of about 1,500 meters, and visibility was 5,000 meters. From 9:41 to 10:17 a.m., MiG-15s practiced formation flying. After landing, they taxied back to the take-off point and refueled from four tank trucks between 10:25 and 10:45 a.m. At 10:55, the planes again took off at intervals of about 100 meters. Heavy flying by MiG-15s continued until h p.m. At 6:05 p.m., two of the six alert planes took off and landed again at 6:13 p.m. 3 October. There was no flying. 4 October. After 8:30 a.m., six MiG-15s were successively towed by a truck to the target range in forest district 50, from where short bursts of machine gum fire were subsequently heard. After 4 p.m., all MiG-15s were towed by two trucks to the runway, from where they took off at 6 p.m. Flying continued until 10 p.m., when heavy rain set in. 5 October. There was no flying in the morning, when the weather was rainy. At	
1	ceiling was at an altitude of about 1,500 meters, and visibility was 5,000 meters. From 9:41 to 10:17 a.m., MiG-15s practiced formation flying. After landing, they taxied back to the take-off point and refueled from four tank trucks between 10:25 and 10:45 a.m. At 10:55, the planes again took off at intervals of about 100 meters. Heavy flying by MiG-15s continued until h p.m. At 6:05 p.m., two of the six alert planes took off and landed again at 6:13 p.m. 3 October. There was no flying. 4 October. After 8:30 a.m., six MiG-15s were successively towed by a truck to the target range in forest district 50, from where short bursts of machine gum fire were subsequently heard. After h p.m., all MiG-15s were towed by two trucks to the runway, from where they took off at 6 p.m. Flying continued until 10 p.m., when heavy rain set in. 5 October. There was no flying in the morning, when the weather was rainy. At 6:30 p.m., two alert planes took off and landed again about 6:40 p.m. Radio trucks, fire trucks and jeeps were parked at the take-off point as observed	
1	ceiling was at an altitude of about 1,500 meters, and visibility was 5,000 meters. From 9:41 to 10:17 a.m., MiG-15s practiced formation flying. After landing, they taxied back to the take-off point and refueled from four tank trucks between 10:25 and 10:45 a.m. At 10:55, the planes again took off at intervals of about 100 meters. Heavy flying by MiG-15s continued until h p.m. At 6:05 p.m., two of the six alert planes took off and landed again at 6:13 p.m. 3 October. There was no flying. 4 October. After 8:30 a.m., six MiG-15s were successively towed by a truck to the target range in forest district 50, from where short bursts of machine gum fire were subsequently heard. After 4 p.m., all MiG-15s were towed by two trucks to the runway, from where they took off at 6 p.m. Flying continued until 10 p.m., when heavy rain set in. 5 October. There was no flying in the morning, when the weather was rainy. At 6:30 p.m., two alert planes took off and landed again about 6:40 p.m. Radio trucks, fire trucks and jeeps were parked at the take-off point as observed during flying activity. However, there was no flying.	
1	ceiling was at an altitude of about 1,500 meters, and visibility was 5,000 meters. From 9:41 to 10:17 a.m., MiG-15s practiced formation flying. After landing, they taxied back to the take-off point and refueled from four tank trucks between 10:25 and 10:45 a.m. At 10:55, the planes again took off at intervals of about 100 meters. Heavy flying by MiG-15s continued until h p.m. At 6:05 p.m., two of the six alert planes took off and landed again at 6:13 p.m. 3 October. There was no flying. 4 October. After 8:30 a.m., six MiG-15s were successively towed by a truck to the target range in forest district 50, from where short bursts of machine gun fire were subsequently heard. After 4 p.m., all MiG-15s were towed by two trucks to the runway, from where they took off at 6 p.m. Flying continued until 10 p.m., when heavy rain set in. 5 October. There was no flying in the morning, when the weather was rainy. At 6:30 p.m., two alert planes took off and landed again about 6:40 p.m. Radio trucks, fire trucks and jeeps were parked at the take-off point as observed during flying activity. However, there was no flying. 6 October. At 8 a.m., six MiG-15s were counted near the runway in forest district 50, while the remainder of the MiG-15s were parked in front of the	
1	ceiling was at an altitude of about 1,500 meters, and visibility was 5,000 meters. From 9:41 to 10:17 a.m., MiG-15s practiced formation flying. After landing, they taxied back to the take-off point and refueled from four tank trucks between 10:25 and 10:45 a.m. At 10:55, the planes again took off at intervals of about 100 meters. Heavy flying by MiG-15s continued until h p.m. At 6:05 p.m., two of the six alert planes took off and landed again at 6:13 p.m. 3 October. There was no flying. 4 October. After 8:30 a.m., six MiG-15s were successively towed by a truck to the target range in forest district 50, from where short bursts of machine gun fire were subsequently heard. After 4 p.m., all MiG-15s were towed by two trucks to the runway, from where they took off at 6 p.m. Flying continued until 10 p.m., when heavy rain set in. 5 October. There was no flying in the morning, when the weather was rainy. At 6:30 p.m., who alert planes took off and landed again about 6:40 p.m. Radio trucks, fire trucks and jeeps were parked at the take-off point as observed during flying activity. However, there was no flying. 6 October. At 8 a.m., six MiG-15s were counted near the runway in forest district 50, while the remainder of the MiG-15s were parked in front of the flight control station. There was no flying.	
	ceiling was at an altitude of about 1,500 meters, and visibility was 5.000 meters. From 9:41 to 10:17 a.m., MiG-15s practiced formation flying. After landing, they taxied back to the take-off point and refueled from four tank trucks between 10:25 and 10:45 a.m. At 10:55, the planes again took off at intervals of about 100 meters. Heavy flying by MiG-15s continued until h p.m. At 6:05 p.m., two of the six alert planes took off and landed again at 6:13 p.m. 3 October. There was no flying. 4 October. After 8:30 a.m., six MiG-15s were successively towed by a truck to the target range in forest district 50, from where short bursts of machine gum fire were subsequently heard. After h p.m., all MiG-15s were towed by two trucks to the runway, from where they took off at 6 p.m. Flying continued until 10 p.m., when heavy rain set in. 5 October. There was no flying in the morning, when the weather was rainy. At 6:30 p.m., two alert planes took off and landed again about 6:h0 p.m. Radio trucks, fire trucks and jeeps were parked at the take-off point as observed during flying activity. However, there was no flying. 6 October. At 8 a.m., six MiG-15s were counted near the runway in forest district 50, while the remainder of the MiG-15s were parked in front of the flight control station. There was no flying. 7 October. At 6:30 a.m., source observed 18 MiG-15s near the runway and an undetermined number of aircraft in front of the flight control station. There	
	ceiling was at an altitude of about 1,500 meters, and visibility was 5,000 meters. From 9:41 to 10:17 a.m., MiG-15s practiced formation flying. After landing, they taxied back to the take-off point and refueled from four tank trucks between 10:25 and 10:45 a.m. At 10:55, the planes again took off at intervals of about 100 meters. Heavy flying by MiG-15s continued until h p.m. At 6:05 p.m., two of the six alert planes took off and landed again at 6:13 p.m. 3 October. There was no flying. 4 October. After 8:30 a.m., six MiG-15s were successively towed by a truck to the target range in forest district 50, from where short bursts of machine gum fire were subsequently heard. After h p.m., all MiG-15s were towed by two trucks to the runway, from where they took off at 6 p.m. Flying continued until 10 p.m., when heavy rain set in. 5 October. There was no flying in the morning, when the weather was rainy. At 6:30 p.m., two alert planes took off and landed again about 6:40 p.m. Radio trucks, fire trucks and jeeps were parked at the take-off point as observed during flying activity. However, there was no flying. 6 October. At 8 a.m., six MiG-15s were counted near the runway in forest district 50, while the remainder of the MiG-15s were parked in front of the flight control station. There was no flying. 7 October. At 6:30 a.m., source observed 18 MiG-15s near the runway and an undetermined number of aircraft in front of the flight control station. There was individual flying from 8:30 a.m., to 5 p.m.	
	ceiling was at an altitude of about 1,500 meters, and visibility was 5.000 meters. From 9:41 to 10:17 a.m., MiG-15s practiced formation flying. After landing, they taxied back to the take-off point and refueled from four tank trucks between 10:25 and 10:45 a.m. At 10:55, the planes again took off at intervals of about 100 meters. Heavy flying by MiG-15s continued until h p.m. At 6:05 p.m., two of the six alert planes took off and landed again at 6:13 p.m. 3 October. There was no flying. 4 October. After 8:30 a.m., six MiG-15s were successively towed by a truck to the target range in forest district 50, from where short bursts of machine gum fire were subsequently heard. After h p.m., all MiG-15s were towed by two trucks to the runway, from where they took off at 6 p.m. Flying continued until 10 p.m., when heavy rain set in. 5 October. There was no flying in the morning, when the weather was rainy. At 6:30 p.m., two alert planes took off and landed again about 6:h0 p.m. Radio trucks, fire trucks and jeeps were parked at the take-off point as observed during flying activity. However, there was no flying. 6 October. At 8 a.m., six MiG-15s were counted near the runway in forest district 50, while the remainder of the MiG-15s were parked in front of the flight control station. There was no flying. 7 October. At 6:30 a.m., source observed 18 MiG-15s near the runway and an undetermined number of aircraft in front of the flight control station. There	
1 [meters. From 9:41 to 10:17 a.m., MiG-15s practiced formation flying. After landing, they taxied back to the take-off point and refueled from four tank trucks between 10:25 and 10:45 a.m. At 10:55, the planes again took off at intervals of about 100 meters. Heavy flying by MiG-15s continued until h p.m. At 6:05 p.m., two of the six alert planes took off and landed again at 6:13 p.m. October. There was no flying. October. After 8:30 a.m., six MiG-15s were successively towed by a truck to the target range in forest district 50, from where short bursts of machine gum fire were subsequently heard. After h p.m., all MiG-15s were towed by two trucks to the runway, from where they took off at 6 p.m. Flying continued until 10 p.m., when heavy rain set in. October. There was no flying in the morning, when the weather was rainy. At October. There was no flying in the morning, when the weather was rainy. At October. There was no flying in the morning when the weather was rainy. At October. There was no flying in the morning when the runway in forest october. At 8 a.m., six MiG-15s were counted near the runway in forest october. At 8 a.m., six MiG-15s were counted near the runway and an october. At 6:30 a.m., source observed 18 MiG-15s near the runway and an october. At 6:30 a.m., source observed 18 MiG-15s at the runway and 1 Yak-11	
1 [meters. From 9:41 to 10:17 a.m., MiG-15s practiced formation flying. After landing, they taxied back to the take-off point and refueled from four tank trucks between 10:25 and 10:45 a.m. At 10:55, the planes again took off at intervals of about 100 meters. Heavy flying by MiG-15s continued until h p.m. At 6:05 p.m., two of the six alert planes took off and landed again at 6:13 p.m. October. There was no flying. October. After 8:30 a.m., six MiG-15s were successively towed by a truck to the target range in forest district 50, from where short bursts of machine gum fire were subsequently heard. After h p.m., all MiG-15s were towed by two trucks to the runway, from where they took off at 6 p.m. Flying continued until 10 p.m., when heavy rain set in. October. There was no flying in the morning, when the weather was rainy. At October. There was no flying in the morning, when the weather was rainy. At October. There was no flying in the morning when the weather was rainy. At October. There was no flying in the morning when the runway in forest october. At 8 a.m., six MiG-15s were counted near the runway in forest october. At 8 a.m., six MiG-15s were counted near the runway and an october. At 6:30 a.m., source observed 18 MiG-15s near the runway and an october. At 6:30 a.m., source observed 18 MiG-15s at the runway and 1 Yak-11	
	meters. From 9:41 to 10:17 a.m., MiG-15s practiced formation flying. After landing, they taxied back to the take-off point and refueled from four tank trucks between 10:25 and 10:15 a.m. At 10:55, the planes again took off at intervals of about 100 meters. Heavy flying by MiG-15s continued until h p.m. At 6:05 p.m., two of the six alert planes took off and landed again at 6:13 p.m. took off and landed again at 6:13 p.m. took off and landed again at 6:13 p.m. October. After 8:30 a.m., six MiG-15s were successively towed by a truck to the target range in forest district 50, from where short bursts of machine gum fire were subsequently heard. After h p.m., all MiG-15s were towed by two trucks to the runway, from where they took off at 6 p.m. Flying continued until 10 p.m., totober. There was no flying in the morning, when the weather was rainy. At to 10 p.m., two alert planes took off and landed again about 6:40 p.m. Radio trucks, fire trucks and jeeps were parked at the take-off point as observed during flying activity. However, there was no flying. October. At 8 a.m., six MiG-15s were counted near the runway in forest district 50, while the remainder of the MiG-15s were parked in front of the flight control station. There was no flying. October. At 6:30 a.m., source observed 18 MiG-15s near the runway and an undetermined number of aircraft in front of the flight control station. There was individual flying from 8:30 a.m., to 5 p.m. October. At 6:50 a.m., source observed 21 MiG-15s at the runway and 1 Yak-11 In front of the flight control station. There was rainy, and the ceiling was at an altitude of about 800 meters.	2
(1	meters. From 9:41 to 10:17 a.m., MiG-15s practiced formation flying. After landing, they taxied back to the take-off point and refueled from four tank trucks between 10:25 and 10:45 a.m. At 10:55, the planes again took off at intervals of about 100 meters. Heavy flying by MiG-15s continued until h p.m. At 6:05 p.m., two of the six alert planes doctober.	

		~ 2 ·	25X1
)	-	Take-off at Landing at	
25X1		Wednesd resonance (College College Col	
		12:47 p.m., 1:20 p.m., 1:26 "	
		After the planes had landed, the pilots rode in trucks to the flight	
		control station. The planes refueled and probably took off again with	
25X1		other pilots. Source observed that aircraft took off about 2 p.m. Flying continued throughout the afternoon. No formation flying was observed.	
		12 October. Twenty-four MiG-15s and one Yak-11 were counted at the field, It was observed that 18 of the planes were covered with tarpaulins, There	
		vas no flying. 15 October. There was no change in the status of the field. The weather	
05)(4		was rainy and the ceiling was at an altitude of 300 to 400 meters. From	
25X1		noon to 1 p.m., MiG-15s practiced individual flying.	
		16 October. There was no flying.	
		17 October. The cloud base was at an altitude of 1,000 meters, and	
		visibility was 500 meters. There was no flying. At 11 a.m., the engines of the alert planes were started.	10
		18 through 20 October, There was no flying.	
		21 October. Eighteen take-offs and landings by individual MiG-15s were observed from 10:30 a.m. to 3 p.m. The weather was rainy, the ceiling was	
		at an altitude of 2,000 meters, and visibility was about 250 meters.	
251/4		22 October. Weather conditions were the same as on the preceding day. At 5 p.m., alert planes took off to circle over the field. No	
25X1		other flying was observed.	
		23 October, There was no flying. The weather was rainy,	
		24 October. At noon, 22 MiG-15s were observed at the runway and two MiG-15s in front of the flight control station. From noon to 12:35 p.m., MiG-15s	
25X1		practiced flying. They were subsequently refueled. At 1:15	40.5
25X1		took off. Between 1:30 and 1:40 p.m., these planes crossed the field	25X1
23/1		in formations of two and landed between 1:45 and 1:51 p.m. All of them	
		were fitted with auxiliary fuel tanks. 27 through 30 October, A total of 24 MiG-15s was observed. Flying was	
		conducted on 20 and 30 October. On the latter day, formations of four	
		to nine planes were seen. At 3:30 p.m., an IL-10 towing a sleeve target landed.	
		31 October, wight alert planes were observed for the first time at the	
		field, 1	
	2.	On 16 October, four AA guns with a caliber of 70 to 80 mm were observed at the emplacement near hosenhof. 2	
25X1	3.	On 2 October, the searchlight mounted on truck was still	
		seen in forest district 28/29. At 8 a.m. on 6 October, 30 soldiers began	
		dismantling the lighting facilities on the north side of the runway. The lamps along the south side of the runway were not removed.	
	89.		
	4.	No aircraft crates arrived during the period from 2 through <u>8 October</u> . Fuel shipments were observed arriving. On 8 October, truck	25X1
		was seen proceeding toward Rosenhof, On 24 October, tank trucks	25X1
25X1		and proceeded toward the flight control station.	
		At 10 a.m. on 12 October, four to six MiC-15s and two green single-engine,	
 25X1	」 「	low-wing monoplanes fitted with in-line engines were observed at the field.	
		There was no flying between 10 a.m. and 1 p.m. in spite of good weather.	

SECRET

Approved For Release 2003/06/19 : CIA-RDP82-00457R015700220002-6

5. Source learned from an airfield worker that six trainers were stationed at the field in addition to the MiG-15s. 7. On 12 October, two boxcars and eight flatcars loaded with tractors truck and two trailers arrived at Brandenburg-Altstadt railroad station en route from Dallgow. At 4 p.m. on 14 October, the shipment was forwarded to Briest. Ten railroad carloads of timber, which arrived at Brandenburg-Altstadt railroad station en route from Netzeband on 30 October were distributed at Zerbst airfield (one carload); at Koethen airfield (three carloads); Merseburg airfield (four carloads); at Merseburg airfield (two carloads). On 30 October, a railroad tank car dispatched in Velten arrived at the railroad station	
25X1 25X1	
at the field in addition to the MiG-15s. 7. On 12 October, two boxcars and eight flatcars loaded with tractors 25X1 25X1 25X1 25X1 25X1 25X1 25X1 25X	25X1
at the field in addition to the MiG-15s. 7. On 12 October, two boxcars and eight flatcars loaded with tractors 25X1 25X1 25X1 25X1 25X1 25X1 25X1 25X	
at the field in addition to the MiG-15s. 7. On 12 October, two boxcars and eight flatcars loaded with tractors 25X1 25X1 25X1 25X1 25X1 25X1 25X1 25X	3
truck and two trailers arrived at Brandenburg-Alt- stadt railroad station en route from Dallgow. At 4 p.m. on 14 October, the shipment was forwarded to Briest. Ten railroad carloads of timber, which arrived at Brandenburg-Altstadt railroad station en route from Netzeband on 30 October were distributed at Zerbst airfield (one carload); at Koethen airfield (three carloads); 25X1 Merseburg airfield (two carloads). On 30 October, a railroad tank car	
arrived at Brandenburg-Altstadt railroad station en route from Netzeband on 30 October were distributed at Zerbst airfield (one carload); at Koethen airfield (three carloads); 25X1 at Zerbst airfield (four carloads); at Merseburg airfield (two carloads). On 30 October, a railroad tank car	25X1
25X1 (one carload); at Koethen airfield (three carloads); 25X1 at Zerbst airfield (four carloads); at Merseburg airfield (two carloads). On 30 October, a railroad tank car	
Merseburg airfield (two carloads). On 30 October, a railroad tank car	25X1 25X1
25X1 consigned at Briest airfield, 25X1	25X1
25X1 1. Comment, A fighter regiment is stationed at Brandenburg-briest airfield, With regard to the training status of this regiment it is noteworthy that flying was conducted under the poor weather conditions prevailing on 21 October.	
25X1 2. Comment. According to available information, four 37-mm AA guns were	
believed to be stationed at the field. As previous observations indicate that six guns are assigned to light AAA batteries, it is indeed more probable that the AAA employement at Rosenhof is occupied by a battery of medium guns.	
25X1 3. Comment, White lamps were previously installed on the north side of the runway, It is unknown why these lamps were dismantled. Generally, runways in East Germany are fitted with only one row of lamps.	
25X1 4.	*
* ×	

SECRET